




Location ID	Date Sampled	Cadmium	Copper	Lead	Manganese	Zinc
32nd St Br	8/5/2015	0.178	1.7	0.24	105	43.5
32nd St Br	8/6/2015	0.16	1.56		105	37.8
32nd St Br	8/6/2015	0.19	1.62	0.115	97.8	49.1




Location: 32nd Street Bridge




Location ID	Date Sampled	Cadmium	Copper	Lead	Manganese	Zinc
A68	8/5/2015	0.828	3.45	0.232	737	199
A68	8/5/2015	0.815	3.16	0.283	727	238
A68	8/5/2015	0.974	3.52	0.82	757	324
A68	8/6/2015	0.85	3.26	0.329	817	326




on: A68




Location ID	Date Sampled	Cadmium	Copper	Lead	Manganese	Zinc
A72	8/5/2015	1.81	9.27	0.225	1370	699
A72	8/5/2015	15.2	1410	50.7	6650	4020
A72	8/5/2015	4.29	205	3.12	1810	1210
A72	8/5/2015	2.59	11.4	0.118	1320	733
A72	8/6/2015	2.11	7.63		1160	609






Location ID	Date Sampled	Cadmium	Copper	Lead	Manganese	Zinc
Bakers Bridge	8/5/2015	0.353	2.28		306	85.8
Bakers Bridge	8/6/2015	0.336	1.88		296	110
Bakers Bridge	8/6/2015	5.32	189	1.56	2090	1700



Location: Bakers Bridge



Location ID	Date Sampled	Cadmium	Copper	Lead	Manganese	Zinc
CC48	8/5/2015	30.6	2260	73.9	10900	8540
CC48	8/5/2015	19.1	1130	54.1	8020	5820
CC48	8/6/2015	14.2	786	30	6720	4650

